HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

U.S. NAVAL BASE, PEARL HARBOR, TYPE "B" CASUALTY DRESSING & DECONTAMINATION STATION (U.S. Naval Base, Pearl Harbor, Naval Shipyard, Facility No. 207) Intersection of Eighth Street, Avenue E & Central Avenue Pearl Harbor Honolulu County Hawaii

HABS HI-470

INDEX TO BLACK AND WHITE PHOTOGRAPHS

David Franzen, photographer, March 2001

HI-470-1	Oblique view of the west side, view facing south-southeast
HI-470-2	Oblique view of east side and south end, view facing northwest
HI-470-3	Oblique view of the north end and east side, view facing southwest
HI-470-4	Partial view of east side, view facing south-southeast
HI-470-5	View of west side, taken from second floor of Facility 1C, view facing east-southeast
HI-470-6	View of entry on the west side, at the northern end of the building, view facing east
HI-470-7	Interior overview of central room on the east side, view facing south
HI-470-8	Interior of niche with small sink and cabinets behind original nurses' station
HI-470-9	Interior of east side exit, view facing east-southeast